

DEPARTMENT OF PUBLIC WORKS  
**CITY OF KAUKAUNA**  
KAUKAUNA, WISCONSIN

KENNETH A. SCHOENIKE  
CITY ENGINEER



August 4, 1976

RECEIVED DNR

AUG 5 1976

Lake Mich. Dist.

Department of Natural Resources  
P.O. Box 3600  
Green Bay, WI 54303

ATTN: Mr. Gary Kulibert  
Solid Waste Management Coordinator

Dear Gary:

The City of Kaukauna has received several complaints about possible leachate from Lehrer's Landfill surfacing on the north side of 20th Street, east of Oakridge Avenue.

Per our conversation of August 2, 1976, I would appreciate your visiting the site and your determination.

If you have any further questions, feel free to contact this office.

Sincerely,

Ken Schoenike, P.E.  
City Engineer

KS/smb  
cc Alderman Henry Drechsler  
Alderman Robert Gertz

00957

*Dr. Buchanan -  
Lehrer.*

OFFICE MEMO

SUBJECT: Lehrer Landfill Inspection-Kaukauna, Wis.

4400

On August 3, 1976, at 2:00 p.m. Gary Kulibert and I investigated a complaint to this office by Mr. Spreeman, Kaukauna, Wisconsin. The complaint concerned leachate seeping from the Lehrer landfill in Kaukauna on to property owned by Mr. Spreeman. Investigation showed that leachate was flowing from the landfill, and produced a specific conductivity of 4000 mhos. at 23°C.

At 6:15 p.m. I returned to the site (8-3-76) and found the refuse left uncovered (see pictures). Barrels examined were empty and had formerly contained adhesives. All heavy equipment used on the site was removed and dumping of refuse had ceased although the gate was still open.

At 6:15 a.m. on August 4, 1976, a return investigation showed the material from the previous night had been left uncovered (see pictures).

*Terrence L. Gardon*

Terrence L. Gardon  
Natural Resources Technician

TLG:ct

8/4/76



00956



Leach Site °C = 24

Asec. Canal #3800-4000

TG. - C.K. August. 3, 1976 2:00 - 2:30 P.M.  
20 Ch. Street.

Leachates coming through onto prop.  
owned by Spreeman. 542. Well  
flowing.  
250' from Berna

check barrels.  
photograph fill.  
gate.

water flowing into fill. —  
sludge being poured into fill. off corner.  
standing water in fill. Extremely poor  
operation.